Hogan & Hartson 89277.0040 Toshihiko YAMASHITA Engine Control Device EV 507 672 177 US 12 Drawing Sheets; Sheet 1 of 12




FIG. 1

Hogan & Hartson 89277.0040 Toshihiko YAMASHITA Engine Control Device EV 507 672 177 US 12 Drawing Sheets; Sheet 2 of 12




FIG.




FIG.





FIG. 4



T.




FIG. 6

Hogan & Hartson 89277.0040 Toshihiko YAMASHITA Engine Control Device EV 507 672 177 US 12 Drawing Sheets; Sheet 7 of 12




FIG. 7




FIG. 8

Hogan & Hartson 89277.0040 Toshihiko YAMASHITA Engine Control Device EV 507 672 177 US 12 Drawing Sheets; Sheet 8 of 12




FIG. 9




FIG. IC

Hogan & Hartson 89277.0040 Toshihiko YAMASHITA Engine Control Device EV 507 672 177 US 12 Drawing Sheets; Sheet 10 of 12




FIG. 11




FIG. 12




FIG. 1




FIG. L

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

□ BLACK BORDERS
□ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
□ FADED TEXT OR DRAWING
□ BLURRED OR ILLEGIBLE TEXT OR DRAWING
□ SKEWED/SLANTED IMAGES
□ COLOR OR BLACK AND WHITE PHOTOGRAPHS
□ GRAY SCALE DOCUMENTS
□ LINES OR MARKS ON ORIGINAL DOCUMENT
□ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
□ OTHER:

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.